

- **1.1** Profil MOD-100 (item 1.1)
- 1.2 Profil MOD-100 (item 1.2)
- 1.3 Wkręt blokujący
- 2. Taśma LED*
- 3. Dławnica*
- 4. Zasilacz (12 V / 24 V)*
- 5. Osłona*
- 6. Zawieszka*
- 7. Dławnica*
- 8. Zaślepka*
- 9. Wkręt

- 10. Zawieszka sufitowa*
- 11. Linka stalowa*
- 12. Odbłyśnik*
- 13. Osłona*

- 18049


NOTE! All LED tapes must be connected to a 12 V or 24 V power supply.

IMPORTANT: Not all possible mounting procedures are presented here. More mounting procedures and related accessories can be found at www.KlusDesign.eu. Drawings of extrusions and accessories in these instructions are simplified and only approximate the actual shapes.

www.KlusDesign.eu 1


^{*}The full range of accessories and electronics is available at www.KlusDesign.eu





Shorten the extrusion item (1.1) by 12 mm / 0.47" relative to item (1.2).

Shorten the reflectors (12) by 12mm / 0.47" (to make them as long as the extrusion item 1.1)




- a. Drill holes for locking bolts in the profiled auxiliary line.The required number of holes is:
- 2 / 1m of the profile 4 / 2m of the profile 6 / 3m of the profile
- b. Drill a hole for the gland.


Ш

Install the LED tapes (2), insert the gland (3) and feed the power cable through it.







Mount the power supply (4) on the back of the extrusion.




- a. Drill two holes for the fasteners in the channel on the back of the extrusion (1.2). They do not have to be in a specific location.
- b. In the channel on the back of the extrusion drill a hole for the gland. minimal distance between the hole and the edge of the extrusion is 8 mm / 0.31".
- c. Drill a hole for the gland near the channel, where you will run the power cable from the ceiling.




a. On both sides, from the side of the profile cross-section, thread the sockets for end cap bolts to a depth of approx. 15 mm / 0.59". (M3 tap)











Install the LED tape (2).

Then connect the poles of the tape using a soldering iron and short wires.

Mount the gland (3) and feed the power cable through it.




Attach the cover (5) between the holes for the fasteners leaving 5 mm space between the cover sections.




Attach the fasteners (6) and mount the metal gland (7).






Mount end caps (8) and secure them with bolts (9).

NOTE! The end caps can also be mounted at stage XIV.



Fasten the extrusion on steel wires (11) to the ceiling fasteners (10). The suspension length can be adjusted by pressing the upper part in the fastener body (6).

Feed the main power cable through the metal gland (7) and tighten the top nut.




Connect the power supply (4) to the power cable.

Connect both extrusion items (1.1, 1.2) by inserting and moving item (1.1) as shown in the figure.


www.KlusDesign.eu 5

MOD-100 mounting instructions






Secure the extrusion item (1.1) against slipping out by screwing the locking bolts (1.3) into the pre-drilled holes.



Mount the reflectors (12).

Mount the bottom cover by slightly bending one wall of the extrusion (13).

The cover needs to be the same legth as the extrusion.



www.KlusDesign.eu 6