

Parts needed to mount the PIKO extrusion



Extrusion (A)



End caps (B)



Cover (C)




LED strip (D)

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Run the cable to the power source.



2. Apply double-sided tape to the extrusion (A), and attach the extrusion to the surface. Connect power. Connect power.

